

STONEY TRAIL AGGREGATE RESOURCE

BLV GROUP

July 17, 2018
5:00pm – 6:00pm
STAR Main Office

Meeting - BLV Semi-Annual Stakeholder Meeting

Attendees - Mike Edwards, Samantha Wright, Bill Corbett - Stakeholders
Wes Markus, Wes Koyzan – BLV Group
Shahid Gill, Glen Murray – Alberta Transportation

Meeting Minutes

- Round Table Discussion on Issues, Actions, and Performance of the Group.
- Recap Operations
 - a. Four Operational Crushers
 - i. Two crushers from 6:00am-6:00pm (Crushing 7:00am-5:00pm)
 - ii. One Crusher from 6:00am-10:00pm (Crushing 7:00am-9:00pm)
 - iii. One Crusher from 6:00am – 12:00am (Crushing 7:00am-11:00pm)
 - b. One Wash plant
 - i. 6:00am-12:00am (Washing 7:00am-11:00pm)
 - c. Operations Monday – Friday. Sales only on weekends

Open the floor to discuss concerns.

- 1) Noise
 - a. Backup alarms could be heard the prior night at 4am and crushing.
 - i. No Plants at STAR are running at that time. (Please note corrected operating hours above)
- 2) Dust
 - a. Windy days dust can be seen.
 - i. Discussed that monitors are reading well below guidelines
 - ii. Crushers have shut down on multiple occasions before a wind event is triggered.
 - iii. Calcium applied at start of season, second application being applied on July 22, 2018
 - iv. Paved area before scales this season.
 - v. Non-Operational calcium applied on interior slopes.
 - vi. Water Trucks & Sweeper active daily.
 - b. Rocky Ridge Road Monitors
 - i. Discussed who set them up.
 - ii. Samantha will look into it and reply to the Group.
- 3) Trucking
 - a. Trucks have been seen hauling West on Burma Road
 - i. STAR trucks do not go that direction and would use Stoney Trail.

- ii. Asked to contact Wes Markus with truck ASGA numbers or trucking company and unit number if possible.
 - b. Gravel spillage on roads
 - c. Trucks hauling on Country Hills
 - i. All trucks that use Country Hills should only proceed West on Stoney Trail. 112 Ave to Sarcee should be used for all truck traffic heading East on Stoney.
- 4) Calcium in Water Wells
 - a. It was noted that a resident had elevated levels of calcium in their well water, wondering could this be caused by calcium in the pit.
 - i. Potential cause would be from the salt on the roads, which freely flow down the ditches that are mowed by County residents (eliminating the natural filtration).
- 5) Cultural Change
 - a. All residents agree that improvements were noticeable.
 - b. They feel there has been a cultural change at the site and that their issues are being heard and addressed.